

Important Safety Notice

Sport Cap 2.0 by Klean Kanteen®

Details

For safety reasons and in cooperation with US Consumer Product Safety Commission, Klean Kanteen® is recalling the Sport Cap 2.0. Klean Kanteen® has received five consumer reports relating to the spout tip of Sport Cap 2.0 breaking or cracking after being dropped, which could pose a potential choking or ingestion hazard. There have been no incidents of actual choking or ingestion reported. Klean Kanteen® has developed a higher-impact version of the spout that remedies the potential hazard.

Klean Kanteen stainless steel bottles and other caps are not affected by this recall.

Return Procedure

1. Inspect the spout on your Sport Cap 2.0 to determine if it is the version being recalled (see Identification instructions and photos below).
2. If the spout on your cap is the version being recalled discontinue use.
3. Contact Klean Kanteen® to receive a new cap with the redesigned spout.
ONLINE at **www.kleankanteen.com/safetynotice**
Klean Kanteen DIRECT at 1-877-546-9063
L.L.Bean CUSTOMERS at 800-650-5998
4. Consumers will be sent a mailer to return caps. Upon receipt, Klean Kanteen® will send consumers a new cap with the upgraded spout.

Identification



Recalled Sport Cap 2.0s can be identified by the polished (shiny) finish on the top of the spout (see photos).



Replacement caps feature a matte (dull) top surface. The new version can also be identified by a round silver sticker on the backside of the packaging.

Post Until Aug 31, 2010

